
APPENDIX A

PHOTO APPENDIX



Photo 1. Private residence armoring, Adjacent to Pleasure Point Park.



Photo 2. Bluff protection and engineered terraces near Pleasure Point Park.



Photo 3. Beach rubble, looking upcoast towards Pleasure Point Park.



Photo 4. A close-up view of the concrete rubble and rock riprap.



Photo 5. Rock riprap and concrete rubble, looking downcoast.



Photo 6. Wave cut in Purisima formation; marine terrace in background.



Photo 7. Larch Lane emergency armoring, looking downcoast.



Photo 8. Private residence armoring and seawall, west of Larch Lane.



Photo 9. East Cliff Drive cliff face erosion and proposed build-out location.



Photo 10. Stairs and crib wall (retaining wall) at 38th Avenue.



Photo 11. Erosion of the existing cliff face.



Photo 12. Drainage below East Cliff Drive.



Photo 13. Wave cuts in Purisima foundation and drainage below East Cliff Drive.



Photo 14. Residences and parking barricades on East Cliff Drive.



Photo 15. Private residence bluff armoring next to 41st Avenue stairway.



Photo 16. Armoring (private residence) against exposed cliff face, near 41st Avenue.



Photo 17. East Cliff Drive overlook, also known as the “Hook” looking South.



Photo 18. Looking northwest at East Cliff Drive from 41st Avenue overlook.



Photo 19. Looking west past the East Cliff Drive overlook.



Photo 20. A view from the parking area at 41st Avenue and East Cliff Drive, toward the overlook area.



Photo 21. Stairway at 41st Avenue overlook.



Photo 22. Thick Purisima formation with vegetation covering terrace.



Photo 23. Exposed Cypress tree root system due to bluff erosion at 41st Avenue.



Photo 24. Surfer entering beach at 41st Avenue stairway.



Photo 25. A view of the parking area at 41st Avenue and East Cliff Drive.



Photo 26. Looking northeast at 41st Avenue at the Hook Area.



Photo 27. Typical cliff face showing exotic vegetation. Near Manzanita Avenue.



Photo 28. Typical cliff top showing exotic vegetation. Near 34th Avenue.



Photo 29. Algae on existing rock riprap. Looking upcoast from stairway and restroom, near 35th Avenue.



Photo 30. Algae on existing rock riprap. Looking upcoast from stairs near Larch Lane.



Photo 31. Intertidal zone. Looking upcoast from near base of stairway at 38th Avenue.



Photo 32. Tidepools. Looking downcoast from park at 41st Avenue.



Photo 33. Example of riprap revetment footprint in Central California.



Photo 34. Groin at Capitola Beach.