East Cliff Drive

Alternative 1: Present

Soil

Terrace Deposits

Purisima Formation

Stage 1
Same as No Project.

Interlude A
Same as No Project until construction is completed.

East Cliff Drive

Alternative 1: 2012

Soil Nail Structure

Stage 2
Bluff stabilized. No further erosion of bluff face.

East Cliff Drive

Alternative 1: 2027

Stage 3
No change. Maintenance performed as needed.

East Cliff Drive

Alternative 1: 2052

Stage 4
No change. Bluff armoring is monitored and repaired as needed.

Source: Griggs 2001

Alternative 1 Erosion Estimate
Full Bluff Protecerion

Santa Cruz, Claifornia

Figure 6-1

Tetra Tech, Inc.